


Dillingham Airport

Age of Pavement
at 2001 Inspection



Dillingham Airport

Pavement Age

0 - 5
6 - 10
11 - 15
16 - 20
21 - 25
26 - 30
> 30

Age in Years

Minimum PCI for Runway = 70
Minimum PCI for Taxiway and Aprons = 60

[] Branch Identifier

Airport Code: DLG

Site Number 50153.*A